


Field Notice 12345

CONCERN:	Proper disabling of snow detection.	DATE	March 2006
-----------------	--	-------------	-------------------

Problem	Turning the EMS board power OFF, disables the snow detection <u>AND</u> disables the aggressive retry function.
----------------	--

Models Affected:	All HELLFIRE series switch heaters equipped with the EMS option, 
-------------------------	--

Corrective Action	To properly disable snow detection disconnect the precipitation detector at the 4 pin connector and leave the EMS board power ON. 
--------------------------	--