



HOVEY
INDUSTRIES LTD.

2793 Fenton Road
Gloucester, Ontario, Canada K1G 3N3
Telephone (613) 822-1765
FAX (613) 822-1556

Sept 9, 1994

Distribution:

All SH Customers, indicated on attached spreadsheet

- R.A. Wood, USA - Richard Wood
- Hovey Industries Ltd. - D. Gerwing, D. Pagliarello, M. Hunt, L. Azevedo, L. Winn

**FIELD AMENDMENT NOTICE
UNION PACIFIC SH
EXTENDABLE FOUNDATION LEG
PIN
PART # 13346**

Switch Heaters(SH) built for Union Pacific Railroad and shipped Aug 24/94 and Sept 7/94, are experiencing failures of the pin which locks the extendable foundation legs. This poses a potential Safety Hazard.

There are four mild steel pins, one located at each lower corner of the bungalow. These are to be replaced with 1/2" X 6" long, high strength alloy steel bolts, and are supplied for direct replacement.

SH units with the following model and serial numbers are affected;

MODEL#	SERIAL #	SHIPPED TO	CONTACT
SH101515262600	7353-NG-9461	Rawlins, WY	R.L. Dillenburg
	7353-NG-9462	Green River, WY	R.L. Dillenburg
	7353-NG-9463	Green River, WY	R.L. Dillenburg
SH131414262600	7353-NG-9449	Rawlins, WY	R.L. Dillenburg
	7353-NG-9450	Rawlins, WY	R.L. Dillenburg
	7353-NG-9451	Green River, WY	R.L. Dillenburg
	7353-NG-9452	Green River, WY	R.L. Dillenburg
	7353-NG-9453	Green River, WY	R.L. Dillenburg

Sorry for any inconvenience this has caused.

All units shipped from Hovey Industries Ltd. after Sept 12, 1994 are equipped with the alloy steel bolts.

Thank You

Gregor Harris, P. Eng.
Manager of Engineering
HOVEY INDUSTRIES LTD.